

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BL338
NE
1/2-1
0.544 mi.
2871 ft.

VAULT#2442
AVE Z AND WEST 3RD ST
BROOKLYN, NY

NY Spills S106384532
N/A

Site 3 of 3 in cluster BL

Relative:
Higher

SPILLS:

Actual:
14 ft.

Name: VAULT#2442
Address: AVE Z AND WEST 3RD ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0400073 / 2004-07-16
Facility ID: 0400073
Facility Type: ER
DER Facility ID: 238126
Site ID: 294241
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2004-04-02
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2004-04-02
CID: 403
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-04-02
Spill Record Last Update: 2004-07-16
Spiller Name: RON ELLIOT
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 001
Contact Name: ERON ELLIOT
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL E2MIS NO. 152748: APPROX 2 GALS OF WHAT APPEARS TO BE TRANSFORMER OIL ON APPROX 00 GALS OF WATER IN TM2442. HISTORICAL PCB COUNT OF UNIT IS 10 PPM DTD 4/5/94. CLEANUP PENDING LAB RESULT. STRUCTURE WAS PRESSURE TESTED AND DID NOT HOLD PRESSURE. IT IS NOW DETERMINRD THAT THE SPILL IS, INDEED, TRANSFORMER OIL AND THAT THE TRANSFORMER IS A BOTTOM LEAKER. CLEANUP TO BEGIN AS 50-499 PPM PCB. CREW TO REMOVE THE TRANSFORMER. ENV. OPS., REPORTS 330 GALS OF DIELECTRIC FLUID AND 40 GALS OF WATER REMOVED FROM TRANSFORMER BY ASTORIA TANKER. TAG ON TRANSFORMER READS 340 GALS CONTAINED IN UNIT. THIS LEAVES 10 GALS OF DIELECTRIC FLUID UNACCOUNTED FOR. C. Lugo, env. ops mech reports they double washed structure with coagulant & 760 biogen and removed all liqudis with vactor. Transformer was removed by Networks. Removed env. stop tag #08301. Clean up completed."
Remarks: "about 2 gallons of transformer oil spilled due to equipment failure
Caller requests to update from 2 gallons to a ten (10) gallon spill. "
Not reported

All Materials:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Site ID: 294241
Operable Unit ID: 882400
Operable Unit: 01
Material ID: 494865
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported